



Gough Palfinger
66 Industrial Ave
Wacol QLD 4076
Australia
P: 0732715811
M: 0448948410

VLC ANNUAL INSPECTION CERTIFICATE V2

Gough Palfinger

STEP 1 - VLC ANNUAL INSPECTION CERTIFICATE V2

Identifier 100158060

- Please use the crane serial number as the Identifier

VEHICLE DETAILS

Vehicle



Photo Appendix 1

Crane



Photo Appendix 2

Owners Name: Independent Bricklaying Services Pty. Ltd.

Plant Number: N/A

Registration Number: 247 - TPX

Hour Meter Reading: N/A

Odometer Reading: 278,273 Km

Crane Manufacturer: Palfinger

Crane Model: PK 14002 EH

Crane Serial Number: 100158060

Year of Manufacture: 2013

10 Year Inspection Due Date: 13 May 2023

Inspection Address:	Wacol
Inspection Date:	10 Sep 2020
Inspected By:	Matt Shipley

Company: PALFINGER AUSTRALIA

Assessment:

- ☒ The crane as detailed above has been inspected to AS2550.11 and is in a safe working condition.

Inspector Name and Signature:	Signature
Matt Shipley	

Inspection Date:	10 Sep 2020
------------------	-------------

INSPECTION POINTS

Overload system	<input checked="" type="radio"/> Pass
Main boom	<input checked="" type="radio"/> Pass
Outer boom	<input checked="" type="radio"/> Pass
Column	<input checked="" type="radio"/> Pass
Extension booms	<input checked="" type="radio"/> Pass
Hook attachment	<input checked="" type="radio"/> Pass
Hook condition (10% max.)	<input checked="" type="radio"/> Pass
Winch brake operation	<input checked="" type="radio"/> N/A

Winch mounting bolts

☒ **N/A**

Winch gearbox oil level

☒ **N/A**

Rope condition

☒ **N/A**

Wear pads

☒ **Pass**

Pins & bushes

☒ **Pass**

Main boom cylinders

☒ **Pass**

Outer boom cylinders

☒ **Pass**

Extension cylinders

☒ **Pass**

Hydraulic reservoirs & filters

☒ **Pass**

Hydraulic hoses & connections

☒ **Pass**

Hose socks fitted / intact

☒ **Pass**

Oil leaks

☒ **Pass**

Crane subframe

☒ **Pass**

Slew assembly condition

☒ **Pass**

Lifting capacity diagram

☒ **Pass**

Attachment to vehicle

☒ **Pass**

Crane details displayed (ID plate)	<input checked="" type="radio"/> Pass
Controls labeled	<input checked="" type="radio"/> Pass
Control lever operation	<input checked="" type="radio"/> Pass
Correct & complete load chart / fitted	<input checked="" type="radio"/> Pass
Outrigger beam locks	<input checked="" type="radio"/> N/A
Outrigger extension beams	<input checked="" type="radio"/> Pass
Outrigger pads	<input checked="" type="radio"/> Pass
Outrigger extension cylinders	<input checked="" type="radio"/> Pass
Leg valves	<input checked="" type="radio"/> Pass
Leg cylinders	<input checked="" type="radio"/> Pass
Valve and transducer tamperproof seals	<input checked="" type="radio"/> Pass
Park and/or travel brackets	<input checked="" type="radio"/> Pass
Structural condition (visual inspection)	<input checked="" type="radio"/> Pass
Slew limitation	<input checked="" type="radio"/> Pass
Emergency stop/s	<input checked="" type="radio"/> Pass
AUSW lights / buzzer	<input checked="" type="radio"/> Pass

TRAN 2

☒ **Pass**

TRAN 5

☒ **N/A**

Dead man switch fitted

☒ **N/A**

Log Book in vehicle

☒ **Pass**

Operator Manual in vehicle cabin

☒ **Pass**

Q1 / Installers plate attached

☒ **Pass**

LOAD TEST

Kilograms (kg)

977 kg

@ ___ Meters

9.9

PTO

Operation

☒ **Pass**

Warning light

☒ **Pass**

Oil leaks

☒ **Pass**

ADDITIONAL PHOTO'S

group copy #0

STEP 2 - VLC ANNUAL INSPECTION CERTIFICATE V2 Step 2

PALFINGER SERVICE ADMINISTRATION

Are any further repairs required and or recommended?

☒ **No**

Service can now be invoiced.

STEP 3 - VLC ANNUAL INSPECTION CERTIFICATE V2 Step 3

WORKSHOP SERVICE ADMINISTRATION

Workshop Checklist

- ☒ **Step 1 VLC Certificate Reviewed And Approved**
- ☒ **Repairs Completed And Recorded On Tiikr**
- ☒ **Job Can Be Closed**

Comments	Annual Service And Inspection
Date and Time	16-Sep-2020 11:21 AM
Full name of person completing report.	Signature
Tim Cooper	TC

Appendix



Photo Appendix 1



Photo Appendix 2